




Plat of Boundary Survey

being known as part of
 Lots No. 2 & 3, Tract No. 14
 Township of Mentor (now a part of the City of Mentor),
 County of Lake, State of Ohio
 P.P.No. 16D119D000120
 Recorded Title : 2006R026602
 In the name of Reinhold & Virginia Roedig
 0.8940 acres as surveyed
 0.1221 acres in the right-of-way as surveyed

Documents Used:
 Cleveland Trust Subdivision Plat 1938 by Crabbs
 Plat of survey - C.M. Hinsdale parcel - Oct. 5, 1928
 Plat of survey - Jordan Drive - June 30, 1938
 Plat of survey - Lake County Road Map Jordan Drive
 Deed Vol. 19 Pg.158
 Deed Vol. 1071 Pg. 399
 Deed Vol. 61 Pg. 218
 Inst. No. 2005R050080
 Inst. No. 2006R026602



Robert S. & Harriet B. Forbes
 P.P.No. 16D119A000220
 1994R044831

Reinhold & Virginia Roedig
 P.P.No. 16D119D000120
 2006R026602
 0.8940 acres as surveyed
 0.1221 acres in the right-of-way as surveyed

Mario & Roberta Bertone
 P.P.No. 16D119D000110
 2005050080

Painesville Water Works
 V 19 - 158
 V 602 - 5

Basis of Bearings - N 00° 00' 00" E from a point of curvature (calculated) in the centerline of Jordan Drive (60 ft.) to a Pin in a Monument box in the intersection of Jordan Drive (60 ft.) and Headlands Road (50 ft. used).

Field Surveyed on June 11 & 12, 2007
 by: Richard A. Fredrickson & Joshua E. Kazmierczak

Drawn on June 13, 2007
 by: JEK

RAFTER A, LTD.
 land surveying & engineering


10980 LaGrange Road Elyria, Ohio 44035
 Telephone: (440) 309-5275
 Fax: (440) 458-6294
 Email: raftera@oh.rr.com

Richard A. Fredrickson, P.E., P.S.

Richard A. Fredrickson

Ohio Surveyor Registration Number 8285

6-21-07



LEGEND	
+	Called Point
○	Pin Found
⊗	Stone Monument with Drill Hole
●	Rebar Set
⊙	Mag Nail Set
⊠	Pin in Monument Box
⊕	Tree
×	Calculated Point



Prepared for:
 Reinhold & Virginia Roedig
 9525 Headlands Road
 Mentor, Ohio 44060

REVISED 6-20-07