

**PLAT OF SURVEY**  
 CITY OF WILLOUGHBY, LAKE COUNTY, OHIO  
 for: **DICK PARKER**  
 CLIENT \_\_\_\_\_ OWNER \_\_\_\_\_  
 ADDRESS \_\_\_\_\_ STREET \_\_\_\_\_ CITY \_\_\_\_\_ ZIP \_\_\_\_\_

**HARMONDALE ALLOT.**  
 SUBDIVISION **F-34** NAME \_\_\_\_\_ TRACT **27A-32G-65 & 66**  
 1&2 VOL-PG. **KIRTLAND ROAD** LOT \_\_\_\_\_ STREET \_\_\_\_\_  
 SUBLOT NO. \_\_\_\_\_ STREET \_\_\_\_\_ VOL-PG. \_\_\_\_\_ PERM. PARCEL NO. \_\_\_\_\_

**LEGEND**

SANITARY MANHOLE --- (Symbol) --- EXIST. ELEV. --- 100.0 --- PROP. ELEV. --- 100.0  
 STORM MANHOLE --- (Symbol) --- AS BUILT ELEVATION  
 INLET OR CATCH BASIN --- (Symbol) --- INDICATES  
 HYDRANT --- (Symbol) --- DIRECTION OF SURFACE DRAINAGE  
 EXISTING CONTOURS --- (Symbol) ---  
 PROPOSED CONTOURS --- (Symbol) ---

**REMARKS**

ALL BOUNDARY DATA SHOWN WAS OBTAINED FROM (DEEDS, RECORDED SUBDIVISION PLAT OR OTHER PUBLIC RECORDS)  
 LOCATIONS AS SHOWN OF ADJACENT WELLS AND SEPTIC TANKS OBTAINED FROM LAKE COUNTY HEALTH DEPARTMENT

**DESIGN CERTIFICATION**

THIS PLAT WAS PREPARED BY ME, AND IS CORRECT TO THE BEST OF MY KNOWLEDGE AND BELIEF.  
*Handwritten Signature*  
 NAME \_\_\_\_\_ SURVEYOR \_\_\_\_\_ REGISTRATION NO. **60343**

**CHECK LIST**


|                               |   |
|-------------------------------|---|
| NO. OF BEDROOMS               | WATER MAIN SIZE, LOCATION               |
| DIMENSIONS                    | SAN. SEWER SIZE % GR. LOC.              |
| BEARINGS                      | SAN. MH. CAST. ELEV. INV. ELEV.         |
| TIE TO NEAREST STREET         | SAN. CONN. SIZE, LOC. DEPTH             |
| SUBLOT NO. PARCEL NO.         | STORM SEWER SIZE % GR. LOC.             |
| SURROUNDING OWNERS            | STORM MH. CAST ELEV. INV. ELEV.         |
| BLDG. DIMENSIONS FIN GR.      | PAVT TYPE GRADE CURBS                   |
| BLDG. TIES FL'R. GRADES       | GAS LINE LOC. SIZE PRESSURE             |
| APRON TYPE WIDTH THICKNESS    | SEPTIC TANK LOCATION & DUPLICATION AREA |
| SIDEWALK TYPE WIDTH THICKNESS | WELL LOCATION                           |
| CULVERT TYPE DIA., LENGTH     | ISOLATION RADIUS FROM WELL              |
| ROCK OUTCROPPINGS             |   |

| REVISIONS |         |    | PLAN PREPARED BY:                     |                                     |
|-----------|---------|----|---------------------------------------|-------------------------------------|
| NO.       | DATE    | BY | Bj BABCOCK · JONES & ASSOCIATES, INC. |                                     |
| 1         | 3/05/12 | RT | PAINESVILLE, OHIO                     |                                     |
| 2         |         |    | DRAWN BY B.P.                         | SCALE 1"=20' PHONE NO. 440-357-1811 |
| 3         |         |    | CHK'D. H.J.                           | DATE 10/15/09 DRAWING NO.           |
| 4         |         |    | APP'D H.J.                            | 09-004-SPL                          |
| 5         |         |    | CREW CHIEF R.B.                       |                                     |

**"AS BUILT" CERTIFICATION**

I, HEREBY CERTIFY THAT THE CIRCLED GRADES ARE EXISTING FINISH GRADES CHECKED IN THE FIELD ON \_\_\_\_\_, 20\_\_\_\_ AND ARE CORRECT TO THE BEST OF MY KNOWLEDGE AND BELIEF.

REGISTERED SURVEYOR \_\_\_\_\_ REG. NO. \_\_\_\_\_



Bearings are based upon the centerline of Kirtland Road being N 50°07'00"W and are used to denote angles only.

**EXISTING UTILITIES NOTE:**  
 THE SIZE AND LOCATION, BOTH HORIZONTAL AND VERTICAL OF THE UNDERGROUND UTILITIES SHOWN HEREON, HAVE BEEN OBTAINED BY A SEARCH OF AVAILABLE RECORDS. VERIFICATION BY FIELD OBSERVATION HAS BEEN CONDUCTED WHERE PRACTICAL, HOWEVER, BABCOCK, JONES AND ASSOCIATES INC. DOES NOT GUARANTEE THE COMPLETENESS NOR ACCURACY THEREOF.

