

SCHADE SURVEYING COMPANY
 4043 Erie Street Willoughby, Ohio
 Phone 440-951-6454


Lot Split-Lot Consolidation
 for
 Shea-Sullivan

Parcels "A" and "B" are part of Sublot 7 of the Shoreland Subdivision No. 5 as recorded in Volume D of Maps, Page 62 of Lake County Record of Plats. Sublots 14 and 15 are in the Luanna Drive Subdivision recorded in Volume O of Maps, Page 28 of Lake County Record of Plats. Part of Original Willoughby Township Lot No. 10 in Tract No. 16, now the City of Eastlake, Ohio. Bearings are based on the west line of Luanna Drive Subdivision being South 04 degrees 14' 30" West and are used to describe angles only.

File No. 10-1032
 Drawing Name Shea2.zak
 Field Book 68
 Scale one inch equals fifty feet

This Survey satisfies the Minimum Standards for Boundary Surveys in the State of Ohio as codified in Chapter 4733.37 of the Ohio Administrative Code

Willard F. Schade, Jr. 6008 8-11-10
 Willard F. Schade Professional Surveyor 6008



Luanna Drive 50'